State of Wisconsin Department of Natural Resources PO Box 7291, Madison WI 53707-7291 dnr.wi.gov

Wadeable Macroinvertebrate Field Data Report Form 3200-081 (R 8/14)

Page 1 of 2

Instructions: Bold fields must be completed.

Station Summary											
Waterbody Name				Waterbody ID Code			Sample ID (YYYYMMDD-CY-FD)				
SHEBOYGAN RIVER					50700			20180914-20-01			
Sampling Location								Database k 168360366	Key		
SWIMS Station ID 203096 SWIMS Station Name SHEBOYGAN RIVER AT HWY								•			
Latitude 43.7557373	Longitude			Lat/Long Determination Method (circle) SWIMS SWDV GPS				Datum Used if using GPS WGS84 or NAD83			
Basin (WMU) SHEBOYGAN				shed Name OYGAN RIVER				County FOND DU LAC			
Sample and Site Descript					1.0						
Sample Collector (Last Na DAVID BOLHA	ame, First)				roject Name NER LONG-T	ERM TR	END WA	DEABLE RE	FERENCE	STREAM	
Sampling Device		E .			*		2		27	20	
X D-Frame Kick Net Surber Sampler Eckman											
Ponar Artificial Substrate					Hess Sampler Other						
Habitat Sampled				9	2						
		Run		[Pool						
Other Shoreline Composite Proportionally-Sampled Hab							itat				
Littoral Zone Profundal Zone Wetland											
Total Sampling Time (min) Estimated	Area Samp	led (m²)	Numb	er of Sample	s in Com	posite				
3		,5		91	1			Replicate No	o c	of	
Reason For Sampling Least Impacted Re Control Site	L	Baseline Trend			Impact / T	reatment	•		- 15-		
Water Temp. (C) D.O. (mg		sat.) pH (s		Condu	ctivity (umho	os/cm)		Transparer	ncy (cm)		
16.5 9.3 97.6 8.0			0	745			120				
Water Color Clear Turbid Stained					Estimated Stream Velocity (m/s) Slow Moderate (< 0.15 m/s) (0.15 m/s)			e s - 0.5 m/s)	Fast	m/a)	
Measured Velocity	circle units	ircle units Average					-	ge Stream Width of reach (m)			
m/s or f/s			orago ot	().]			(a)				
Composition of Substrate	Sampled (Po	ercent):)•[L	0,0			
	Pouldoro	•		Rubble				0 1	504		
Boulders Bedrock:(basketball or larger):							Gravel (ladybug to te	nnisball):	10		
Sand: Clay:				Silt/Muck: Ove			erhanging Vegetation:				
Aquatic Macrophytes: Leaf Snags:				Coarse Woody Debris:			Other ():				
Embeddedness of Substr	ate at Sample	e Site (%)	20		Canopy Cov	er at Sar	nple Site	(%)	0		